IOS16 CAREAWARE CONNECT MESSENGER UPDATE

9.15.22

Postions Affected

Anyone with an iPhone currently using CareAware Connect Messenger.

Summary:

Updating to the iOS 16 software in iPhone could cause issues within CareAware Connect Messenger.

Key Points:

To avoid issues, make sure you have the **3.22** version of CareAware Connect Messenger from the App Store. This is the most current version of the application.

How do I know which iOS version I have?

1) **Settings**:



2) **General**:



3) Software Update:

 If your Automatic Updates are ON, they will update to the most current version automatically.
Therefore, you will need to ensure that you have the 3.22 Version of CareAware.

Software Update




Downloading 3.22 CareAware:

1) App Store:



2) Search CareAware Connect Messenger and click the name for more information:



- 3) Ensure it says 3.22 before downloading:
 - If you see open, this means that you have already downloaded the most current version and no further action is needed. Otherwise, click download to install the application.

